



NEW MEXICO DEPARTMENT OF ENERGY
AND NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/27/19 Operator Blackhawk Energy Corp API #30-0 39-25 78 2

Property Name JIC 458-6 Well No. 3 Location: Unit G Section 6 Township 30N Range 3W

Has twin well 458-6 #35J 238 PSI on tube.

Well Status (Shut-In or Producing) Initial PSI: Tubing 413 Intermediate Casing 74 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0		74			Steady Flow	
10 min	0		74			Surges	
15 min	0		74			Down to Nothing	✓
20 min						Nothing	
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: H₂S showed 0 H₂S on initial blow down.

BH showed 3 psi on gauge and a 8 second pop down to nothing.
nothing else through out Test. Casing held at 74 psi throughout Test.
BH showed zero on gauge after 5 min shut in and small 1-sec pop.

By Robert Talamante

Witness

Plant/lease

(Position)

E-mail address rtalamante

RECEIVED
SEP 10 2019
DISTRICT III