



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/District III.htm](http://emnr.state.nm.us/ocd/District%20III/District%20III.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/26/2019 Operator Black Hawk Energy Corp API #30-0 39-25788
Property Name Jic 464-30 Well No. 10 ^{NRC} Location: Unit E Section 30 Township 30N Range 34
twin Jic 464-30 #1055 0 on tube
Well Status (Shut-In or Producing) Initial PSI: Tubing 27 Intermediate Casing 215 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0		215			Steady Flow	
10 min	0		215			Surges	
15 min	0		215			Down to Nothing	✓
20 min						Nothing	
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: BH had 1 psi on Gauge went down to nothing in 5 seconds. Casing held steady at 215 psi through out Test. BH nothing through out Test and 0 on shut in.
By Robert Talamante Witness
Plant/lease operator (Position) very small pool

E-mail address rtalamante@blackhawkenergy.com

SEP 10 2019
DISTRICT III