



NEW MEXICO DEPARTMENT OF
NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/27/19 Operator Blackhawk energy corp API #30-0 39-25911

Property Name JIC 458-5 Well No. 355 Location: Unit 0 Section 5 Township 30N Range 3W
twin well JIC 458-5 #3 Tube - 590 PSI
Well Status (Shut-In or Producing) Initial PSI: Tubing 22 Intermediate Casing 22 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0		22			Steady Flow	
10 min	0		22			Surges	
15 min	0		22			Down to Nothing	✓
20 min						Nothing	
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: H2S tube showed 0 H2S on initial blow down.
BH showed 11 psi on gauge, blow down in 5 seconds followed by 2 seconds of visible fumes, nothing else through out Test. Casing held at 22-psi through out Test. BH showed 0 psi after 5 min shut in with a 3 second pool.
By Robert Talamante Witness
Plant/lease operator
(Position)

E-mail address rtalamante@blackhawkenergycorp.com

RECEIVED
SEP 10 2019
DISTRICT III