



NEW MEXICO DEPARTMENT OF ENERGY
OIL CONSERVATION DIVISION

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3district.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/20/2019 Operator Blackhawk API #30-0 392-6232

Property Name Jic 459 Well No. 255 Location: Unit E Section 20 Township 30N Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 23 Intermediate Casing 37 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>37</u>		
10 min	<u>0</u>		<u>37</u>		
15 min	<u>0</u>		<u>37</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Braden Head showed 0 psi, nothing else when opened.
Casing showed 37 psi and held through out Test.
BH had 0 psi after 5 min shut in - nothing else

By Robert Talamante

Witness

Plant / lease operator
(Position)

E-mail address rtalamante@blackhawkenergy.com
NMOC

OCT 07 2019
DISTRICT III