



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/9/19 Operator ENDURING RESOURCES IV LLC API # 30-039-26567

Property Name RINCON UNIT Well No. 166R Location: Unit M Section 32 Township 27N Range 06W

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 60 Intermediate 6 Casing 59 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>6</u>	<u>59</u>	<u>0</u>	<u>59</u>
10 min	<u>0</u>	<u>6</u>	<u>59</u>	<u>0</u>	<u>59</u>
15 min	<u>0</u>	<u>6</u>	<u>59</u>	<u>0</u>	<u>59</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		☒
Nothing	☒	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

intermediate blew down to nothing in approx. 4 seconds

By

[Signature]
HSE Tech
(Position)

Witness

E-mail address

JDockter@EnduringResources.com

NMOC

OCT 16 2019

DISTRICT III

10-15-19