



NEW MEXICO STATE OIL CONSERVATION DIVISION
1000 RIO BRAZOS ROAD
ALBUQUERQUE, NM 87110

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/21/2019 Operator Blackhawk API #30-0 392-7801
Property Name Jic 460-15 Well No. 13 Location: Unit _____ Section 15 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 42 Intermediate _____ Casing 782 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	<u>0</u>		<u>782</u>		
10 min	<u>0</u>		<u>782</u>		
15 min	<u>0</u>		<u>782</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

BH had 0 psi, nothing else at all throughout Test
Casing had 782 psi and held steady.
BH had 0 psi after 5 min shut in and nothing else.

By Robert Talamante

Witness _____

Plant/lease operator
(Position)

E-mail address rtalamante@blackhawkenergy.com
NMOC

OCT 07 2019
DISTRICT III