



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-3-2019 Operator Blackhawk API #30-0 039-29269

Property Name Jic 462-23 Well No. 33 Location: Unit Section 23 Township 30N Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate 90 Casing 340 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>340</u>	<u>0</u>	<u>340</u>
10 min	<u>0</u>	<u>0</u>	<u>340</u>	<u>0</u>	<u>340</u>
15 min	<u>0</u>	<u>0</u>	<u>340</u>	<u>0</u>	<u>340</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>✓</u>	<u>✓</u>
Nothing		
Gas		<u>✓</u>
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Bradenhead had small pool to nothing 1 sec.
Intermediate blew down to nothing in 25 sec.

By Rick Kelly
Lead Plant Operator
(Position)

Witness

E-mail address rkelly@blackhawkenergycorp.com

HMOC
SEP 10 2019
DISTRICT III