



NEW MEXICO DEPARTMENT OF
NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/9/2019 Operator Blackhawk Energy Corp API #30-0 39-29887
Property Name JIC 464-32 Well No. 111 Location: Unit Section 32 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 5 Intermediate Casing 28 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0		28		
10 min	0		28		
15 min	0		28		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE

REMARKS:

BH had 0 psi on gauge and a 1 second pop, nothing else.
Casing had 28 psi and held steady.
BH had 0 psi after 5 min shut in and nothing else.

By Robert Talamante

Witness

Plant/lease operator
(Position)

E-mail address rtalamante@blackhawkenergycorp.com

SEP 10 2019
DISTRICT III