



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/20/19 Operator BlackHawk Energy API #30-0 39-30839

Property Name Jicarilla 29-02-23 Well No. 14 Location: Unit A Section 23 Township 29N Range 2W

Well Status (Shut-In or Producing) Initial PSI: Tubing 13 Intermediate N/A Casing 24 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME	<u>0</u>		<u>24</u>		
5 min	<u>0</u>		<u>24</u>		
10 min	<u>0</u>		<u>24</u>		
15 min	<u>0</u>		<u>24</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR        FRESH        SALTY        SULFUR        BLACK       

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Opened Bradenhead valve 8/19/19 nothing on it.

By

Denny Snell

Lease Operator  
(Position)

Witness

E-mail address dsnell@blackhawkenergy.com

NMOC  
SEP 10 2019  
DISTRICT III