



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 9.16.19 Operator HPOC, LLC API # 30-0 43-21065

Property Name Eagle Springs 9 Federal Well # 1 Location: Unit D Sec 9 Twn 19 Rge 4

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal /
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

NMOCD
SEP 17 2019
DISTRICT III

Temporarily Abandoned Well (Y/N): (N) TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 750
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 560 psi. for 30 mins. Test passed/failed

REMARKS:

Picker Set - 5043
GR Prof - 5087

Requested monitoring of casing
well was bled from 1050 to 0 prior to MIT test.

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02

60 MIN.

NMOCD
SEP 17 2019
DISTRICT III

CHART POOL USA INC.
PORTAGE, INDIANA

METER _____

CHART PUT ON _____

TAKEN OFF _____

LOCATION Eagle Springs 9 Federal #1

REMARKS By 123
removed by PLO
(TO FIT)

Donna Kullback
Wm. J. Lucas
9/16/19

Burke

MT

35

HPCL

08

Eagle Springs 9 Federal #1

92
9/16/19.

B. Lucas