



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOCd

SEP 17 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9.16.19 Operator HPAC, LLC API #30-0 43-21065
Property Name Eagle Springs 9 Federal Well No. 1 Location: Unit D Section 9 Township 19 Range 4
Well Status (Shut-In or Producing) Initial PSI: Tubing 850 Intermediate 11A Casing 1050 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead Int	Csg	INTERM Int	Csg	
TIME						
5 min	<u>0</u>		<u>780</u>			
10 min	<u>0</u>		<u>780</u>			
15 min	<u>0</u>		<u>780</u>			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 11A

REMARKS:

Long puff when opened. Casing bled to 780
prior to opening bh. Nothing when opened after 5
min. shut-in

By David D...

Witness Monica Luehling

(Position)

E-mail address _____