



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 10-16-19 Operator Hilcorp Energy API # 30-0 39-20294
Property Name Jicarilla 101 Well # 3 Location: Unit N Sec 1 Twn 26N Rge 4W
Land Type: State _____ Well Type: _____
Federal _____ NMOC DISTRICT III _____
Private _____ OCT 16 2019 _____
Indian X _____ Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X _____
Pressure observation _____

Temporarily Abandoned Well (~~TA~~ UIC): Post Workover TA Expires: _____

Casing Pres. Ø _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. Ø _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to 610 psi. for 30 mins. Test passed ~~failed~~

REMARKS: Pressured up to 610psi - 610psi at 5min - 610psi at 10min - 610psi at 15min
610psi at 20min - 610psi at 25min - 610psi at 30min -

RBP @ 3710' 1000# spring 1hr clock/chart last on 8-1-19

By Joe McIlhenny (Operator Representative) Witness [Signature] (NMOC)

Site Sup.
(Position)

Revised 02-11-02