



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

DISTRICT III

SEP 11 2019

MOCD

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 9.10.19 Operator Hilcorp Energy API # 30-0 39-23501

Property Name San Juan 30.6 Ut Well # 1124 Location: Unit Sec 26 Twn 30 Rge 6

Land Type:

State
Federal
Private
Indian

Well Type:

Water Injection
Salt Water Disposal /
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N) (Y) TA Expires:

Casing Pres. 0 Tbg. SI Pres. Max. Inj. Pres. 1910
Bradenhead Pres. 0 Tbg. Inj. Pres.
Tubing Pres. 482
Int. Casing Pres. 0

Pressured annulus up to 5460 psi. for 31 mins. Test (passed) failed

REMARKS: 15 minutes to pressure up.
1/2 barrel to fill.
Packer 8163
top perf 8221
Rose to 472 - last 10 minutes of 31 minute test. Hose
heated - well down for 13 hours next test. Shut 12 hours prior - 13 min
to dead

By Jason W. Perkins II Witness Monica Kuehling
(Operator Representative) (NMOC D)
SWD operator
(Position)

Revised 02-11-02