



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

DISTRICT III

SEP 11 2019

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

DOWN

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9.10.19 Operator Hilcorp Energy API #30-0 39-24549
Property Name SS 31.6 lit SWD Well No. 301 Location: Unit 301 Section 6 Township 30 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 938 Intermediate 10 Casing 0 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0	10	0	1	0
10 min	0	10	0	0.8	0
15 min	0	10	0	0	0
20 min				0	0
25 min				0	0
30 min				0	0

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		
Gas	/	/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH. Puff when opened. Nothing when opened after 5 min shut-in. Int. Medium blow really tight blow at 15 dead at 20 minutes.

By [Signature]
JAP Operator
(Position)

Witness Monica Kuehling
Gas Sample.

E-mail address _____

