



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 29 OCT 2019 Operator HILCORP API #30-0 39 07890

Property Name SAN JUAN 30-6 Well No. 67 Location: Unit Section 12 Township 30 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing N/A Intermediate 120 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>120</u>	<u>0</u>	<u>0</u>	<u>0</u>
10 min	<u>0</u>	<u>120</u>	<u>0</u>	<u>0</u>	<u>0</u>
15 min	<u>0</u>	<u>120</u>	<u>0</u>	<u>0</u>	<u>0</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	<u>X</u>
Gas	<u>X</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT BLEW DOWN TO NOTHING
IN 5 MINUTES

By Juan Fudrus
Well Site Supervisor
(Position)

Witness John Dym

E-mail address

NMOC
OCT 30 2019
DISTRICT III