



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 30 OCT 2019 Operator HILCORP API # 30-0 3987890

Property Name SAN JUAN 20-6 Well # 67 Location: Unit ___ Sec 2 Twn 20 Rge 7

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed

REMARKS: 1000 PSI (AIRING) 60 MINUTE CLOCK
THE CASING WAS PRESSURED UP TO 540 PSI AND PRESSURE
FELL TO 540 AND HELD FOR THE LAST MINUTES

By Juan Rodriguez
(Operator Representative)
Wellsite Supervisor
(Position)

Witness John D. Brown
(NMOCD)
NMOCD

OCT 30 2019

DISTRICT III

Revised 02-11-02