



NEW MEXICO HIGHWAY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3/district.htm](http://emnr.state.nm.us/ocd/District%20III3/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/24/19 Operator Black Hawk Engr API #30-0 39-24167
Property Name Jicarilla Well No. 3 Location: Unit H Section 7 Township 30 Range 36
Well Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate N/A Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	/	75		
10 min	0	/	75		
15 min	0	/	75		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS: Shut well in. BH had no pressure.

By Matthew Trojillo
Operator
(Position)

Witness _____

E-mail address mtrojillo@BlackHawk energy.