



OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distr.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-11-19 Operator Black Hawk API #30-0 39-25862
Property Name 458-8 Well No. 10 Location: Unit P Section 8 Township 30 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 35 Intermediate Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>40</u>		
10 min	<u>0</u>		<u>40</u>		
15 min	<u>0</u>		<u>40</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: No Pressure on BH During testing.

By Matthew Trojillo

Witness

(Position)

E-mail address mtrojillo@BlackHawkEnergyCorp.com