



NEW MEXICO OIL & GAS COMMISSION
 1100 W. UNIVERSITY AVENUE, SUITE 1000
 ALBUQUERQUE, NEW MEXICO 87102

OIL CONSERVATION DIVISION
 AZTEC DISTRICT OFFICE
 1000 RIO BRAZOS ROAD
 AZTEC NM 87410
 (505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-11-19 Operator Black Hawk API #30-0 39-26178
 Property Name 458-8 SJ Well No. 10 Location: Unit P Section 8 Township 30 Range 3
 Well Status (Shut-In or Producing) Initial PSI: Tubing 10 Intermediate Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	<u>0</u>		<u>35</u>		
10 min	<u>0</u>		<u>35</u>		
15 min	<u>0</u>		<u>35</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u> </u>	<u> </u>
Surges <u> </u>	<u> </u>
Down to Nothing <u> </u>	<u> </u>
Nothing <u> </u>	<u> </u>
Gas <u> </u>	<u> </u>
Gas & Water <u> </u>	<u> </u>
Water <u> </u>	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: No Pressure on BH During testing
Casing held Pressure During testing

By Matthew Trujillo
Operator
 (Position)

Witness

E-mail address mtrujillo@BlackHawkEnergyCorp.com

NMOC

OCT 29 2019

DISTRICT III