



NEW MEXICO DEPARTMENT OF ENERGY
DIVISION OF OIL CONSERVATION

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-10-19 Operator Black Hawk API #30-0 39-27849
Property Name 458-8 Well No. 15 Location: Unit Section 8 Township 3 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 5 Intermediate 1 Casing 330 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>330</u>		
10 min	<u>0</u>	<u>0</u>	<u>330</u>		
15 min	<u>0</u>	<u>0</u>	<u>330</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>NMOC</u>
Nothing	<u>OCT 29 2019</u>
Gas	<u>DISTRICT III</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

NO Pressure on BH well testing
Casing Pressure held Good.

By Matthew Trujillo
Operator
(Position)

Witness

E-mail address mtrujillo@BlackHawkEnergy.com