



1004 N. 1st St. Suite 100, Santa Fe, NM 87501
Phone: (505) 334-6178 Fax: (505) 334-6170
http://emr.state.nm.us/oilconservation/districtIII/3district.htm

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emr.state.nm.us/oilconservation/districtIII/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-27-19 Operator Black Hawk API #30-0 39-29859

Property Name 459-18 Well No. 112 Location: Unit Section 18 Township 30 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>35</u>		
10 min	<u>0</u>		<u>35</u>		
15 min	<u>0</u>		<u>35</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

BH had very little poof of gas. When open
Blew Down in 10 sec. Casing Pressure held
Good.

By Matthew Trujillo
Operator.
(Position)

Witness

E-mail address mtrujillo@BlackHawkEnergy.com