



OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-6-19 Operator BLACK HAWK API #30-0 39-29889
Property Name Jicarilla Well No. 722 Location: Unit 462-22 Section 22 Township 30 Range 34
Well Status (Shut-In or Producing) Initial PSI: Tubing 15 Intermediate — Casing 80 Bradenhead —

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>8/0</u>		
10 min	<u>0</u>	<u>—</u>	<u>8/0</u>		
15 min	<u>0</u>		<u>8/6</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>NMOC</u>
Nothing	<u>✓</u>
Gas	<u>OCT 29 2019</u>
Gas & Water	<u>DISTRICT III</u>
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS: (Plunger) no pressure on BH. tested
Good.

By Matthew Trujillo
Operator
(Position)

Witness —

E-mail address mtrujillo@BlackHawkEnergy.com