



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

NMOC

NOV 05 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11.5.19 Operator H. Coy Energy API #30-0 45-06149
Property Name Burroughs Corn Well No. 1 Location: Unit Section 36 Township 27 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 1/A Intermediate 1 Casing 25 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	2	7	0	6
10 min	0	0	3	0	6
15 min	0	0	4	0	2
20 min	0	1	6	0	3
25 min	0	2	7	0	7
30 min	0	1	5	0	7

Steady Flow	<u> </u>	<u> </u>
Surges	<u> </u>	<u> </u>
Down to Nothing	<u> </u>	<u> </u>
Nothing	<u> </u>	<u> </u>
Gas	<u> </u>	<u> </u>
Gas & Water	<u> </u>	<u> </u>
Water	<u> </u>	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 6

INTERMEDIATE 6-1

REMARKS:

No tubing - water sample taken 3H. Water immediate
when opened. Casing pecculafes - 13.5 gallons in 30 min.
Int - purg when opened. Started running water at 11 min. dripping
By Chris Abeyta Witness Mona Kuchling at 15 min -
Water sample taken 20 dripping.
25 dripping.
30 dripping -
pint of water -

(Position)

E-mail address