



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 17 JULY 2019 Operator HILCORP API #30-0 45-06149

Property Name BURMILG HS Well No. 1 Location: Unit Section 36 Township 28 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing NA Intermediate 11 Casing 11 Bradenhead 9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	.2	2.9	11	0	12
10 min	.2	.2	11	0	12
15 min	.2	.2	11	0	12
20 min	.1	.1	12		
25 min	.1	.1	12		
30 min	.1	.1	12		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow		
Surges		
Down to Nothing		
Nothing		X
Gas		
Gas & Water		
Water	X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD X 7.4 INTERMEDIATE .3

REMARKS:

OPENED THE BRADENHEAD AND WATER FLOWED FOR THE ENTIRE TEST
MAKING 15 GALLONS OF WATER. OPENED THE INTERMEDIATE AND NOTHING CAME OUT.
REQUESTED A WATER ANALYSIS AND WELL BORE SCHEMATIC

By Jeff Nunez

Witness [Signature]

(Position)

E-mail address

INTERMEDIATE FELL
WHEN THE BRADENHEAD WAS OPEN.

NMOCD

JUL 17 2019

DISTRICT III