



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

NMOCd

AUG 15 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-14-19 Operator Hilcorp Energy Co API #30-0 45-24321
Property Name Cann Well No. 1E Location: Unit 25 Section 25 Township 31 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 97 Intermediate 1A Casing 100 Bradenhead 99

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0		99			
10 min	0		98			
15 min	0		98			
20 min	0		98			
25 min	0		97			
30 min	0		97			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 97

INTERMEDIATE 1A

REMARKS:

Need new sign - missing API - 1/4" x 1/4" knot letter
Hard blow when opened - to lighter at 43 seconds.
Medium blow - 5-10-15-20-25-30.

By SE J

Witness Monica Truckling

(Position)

E-mail address _____

Gas samples taken prior to testing.
Need to find where gas is coming from.