Deviation Report			
Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farmington, NM 87499		
Lease Name and Number (API Number) SAN JUAN 28-6 UNIT #137N (30-039-29670)	Location -2045 FSL -1070 FWL	Sec. Twn. Rge. 14-028N-006W	
Pool and Formation	County	State	
BASIN DAKOTA	RIO ARRIBA	NEW MEXICO	

(OH)

Depth (ft)	Deviation (degrees)	
80	1.00	1000
140	1.00	13 4 3 0 75h
561	1.00	
1,059	1.00	BANVAAAR
1,559	0.25	MAY 2006
2,059	1.00	PECSIVED SI
2,529	1.25	E OL CONS. DIV.
3,029	0.75	E DIST. 3
3,527	0.75	
7,815	1.75	SEEDEN BLUE

Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 2th day of MAY, 2006.

Notary Public in and for San Juan County, New Mexico

My commission expires March 20, 2010.

