



NEW MEXICO DEPARTMENT OF
NATURAL RESOURCES

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/26/19 Operator Blackhawk Energy Corp API #30-0 39-29314
Property Name JIC 458-5 Well No. #22 Location: Unit F Section 5 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 19 Intermediate Casing 940 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0		940		
10 min	0		945		
15 min	0		960		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

BH showed zero on gauge and nothing through out Test.
Casing was shut in 48 hrs before test, showed 940 psi and slowly increased to 960 psi and held. BH showed zero after 5 min shut-in.

By Robert Talamante

Witness

Plant/lease operator
(Position)

E-mail address rtalamante@blackhawkenergy.com

RECEIVED
SEP 18 2019
DISTRICT III