



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOC

DEC 16 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12.13.19 Operator SSR Op. LLC API #30-0 39-05420

Property Name Jewell & Parker 3 Well No. 9 Location: Unit 20 Section 20 Township 24 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing 239 Intermediate N/A Casing 204 Bradenhead 188

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int			
TIME							
5 min	<u>111</u>		<u>190</u>			Steady Flow	
10 min	<u>95</u>		<u>174</u>			Surges <u>at 18 min</u>	
15 min	<u>79</u>		<u>157</u>			Down to Nothing	
20 min	<u>74</u>		<u>150</u>			Nothing	
25 min	<u>67</u>		<u>142</u>			Gas	
30 min	<u>59</u>		<u>135</u>			Gas & Water <u>✓</u>	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 69

INTERMEDIATE N/A

REMARKS:

Blew hard when opened with spit to surging
black water at 18 min through 1/4" valve
3 gallons black produced water

By Jacob Harter Jacob Harter

Witness Monica Kuehling

Consulting

(Position)

E-mail address jharter@coffinwoodconsulting.com



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOC

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

DEC 11 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12.11.19 Operator DSR Op. API #30-0 39-05420
Property Name Scurilla Apache Well No. 9 Location: Unit 20 Section 20 Township 24 Range 5
Well Status (Shut-In or Producing) Initial PSI: Tubing 19 Intermediate N/A Casing 194 Bradenhead 183

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	<u>2</u>		<u>182</u>		
10 min	<u>2</u>		<u>173</u>		
15 min	<u>1</u>		<u>163</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE N/A

REMARKS:

Flowing thru 1/2 inch needle valve - started flowing
Water at 18 minutes - Nothing to Catch water
Re-scheduled test for 12.13.19

By _____

Witness _____

(Position)

Gas samples taken

E-mail address _____