



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

NMOC

DEC 16 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12.13.19 Operator DSPQ Per. LLC API #30-0 39-27533
Property Name Lybrook Yard WSW Well No. 1 Location: Unit 14 Section 14 Township 23 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 553 Intermediate N/A Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>5</u>		
10 min	<u>0</u>		<u>5</u>		
15 min	<u>0</u>		<u>5</u>		
20 min					
25 min					
30 min					

Steady Flow _____
Surges _____
UP Down to Nothing Vacuum
Nothing _____
Gas _____
Gas & Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Vacuum when opened to dead.

K:11900

No well sign at well - up by tank batteries

By Jacob Harter

Witness Mona Kuchling

Consultant

(Position)

E-mail address jharter@cottonwoodconsulting.com