



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

WMOCB

DEC 11 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12.11.19 Operator DJR Per. API #30-0 39-27726
Property Name Jicarilla Hacks B 9E Well No. 9E Location: Unit 20 Section 20 Township 24 Range 5
Well Status (Shut-In or Producing) Initial PSI: Tubing 123 Intermediate N/A Casing 173 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>173</u>		
10 min	<u>0</u>		<u>175</u>		
15 min	<u>0</u>		<u>177</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Puff when opened - nothing when opened
after 5 min shut-in

By Jacob Hester
Consultant
(Position)

Witness

Alonza Kuchling
SOBIA

E-mail address jherst@cottonwoodconsulting.com