



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 6-12-19 Operator BPx API # 3004524988

Property Name Heaton Com Ls 9 Location: Unit I Section 32 Township 31 Range 11
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 12 Intermediate N/A Casing 29 Bradenhead 9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water		
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor									
5 minutes	∅	30	/	/	/									
10 minutes	∅	32												
15 minutes	∅	33												
20 minutes														
25 minutes														
30 minutes														
5 minute SI	∅	35						✓		✓				

NMOCD
JUL 11 2019
DISTRICT III

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead ∅ Intermediate N/A

REMARKS: pulled samples: BH-7036, T- C- 7077. Whisper @ start of test
and down to nothing in 30 sec No flow

By Eugenia Hamilton
Technician

Witness _____

(Position)