

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMSF078215A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on page 28. Well Name and No.
VANDERSLICE 1009. API Well No.
30-045-26907-00-S110. Field and Pool or Exploratory Area
CEDAR HILL FRUITLAND BASAL COA11. County or Parish, State
SAN JUAN COUNTY, NM1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other: COAL BED METHANE2. Name of Operator
HILCORP ENERGY COMPANY
Contact: AMANDA WALKER
E-Mail: mwalker@hilcorp.com3a. Address
1111 TRAVIS STREET
HOUSTON, TX 770023b. Phone No. (include area code)
Ph: 505-324-5122

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 18 T32N R10W NENE 0800FNL 1175FEL
36.990173 N Lat, 107.918076 W Lon

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Workover Operations
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

1/10/2020: (CSG: 13 PSI, TBG: NA) MIRU. ND WH ASSEMBLY. PULL ROD STRING. LATCH ONTO ROD ASSEMBLY, RODS STUCK, PULL TENSION ON RODS. SIW. SL. SDWE.

1/15/2020: (CSG: 20 PSI, TBG: 20 PSI, BH: 0 PSI). WORK TO FREE RODS, POOH W/ROD STRING. PARTED @ SHEAR TOOL. RODS DRY. NU BOP. FUNCTION TEST BOP. TST GOOD. REMOVE TBG HANGER. TIH TAG NO FILL, POSSIBLE PARTED TBG. CONT TOOH & SCAN TBG, SEVERE PITTING ON LAST 2 JTS OF TBG. 1/2 JT TBG, 1 FULL JT TBG, SN & MUD ANCHOR LEFT IN HOLE. MU 4-3/4" JUNK MILL. TIH & TAG @ LINER TOP 2698'. ATT TO WORK INTO LINER W/NO SUCCESS. TOOH, PU 3-7/8" JUNK MILL & TAG @ 2960'. EST TOF @ 2974'. EST CIRC W/AIR PACKAGE. WORK THROUGH F/2960' T/2965'. CO FILL DOWN TO 2985'. ATTEMPT TO WORK DEEPER W/NO SUCCESS. SIW. SL. SDFN.

1/16/2020: (BH: 0 PSI, CSG: 24 PSI) RIH W/94 JTS 2-3/8" 4.7# J-55 TBG. EOT @ 2978'. FN @ 2967'. TOP

14. I hereby certify that the foregoing is true and correct.		DISTRICT III	
Electronic Submission #500369 verified by the BLM Well Information System For HILCORP ENERGY COMPANY, sent to the Farmington Committed to AFMSS for processing by JOE KILLINS on 01/23/2020 (20JK0089SE)			
Name (Printed/Typed)	AMANDA WALKER	Title	OPERATIONS/REGULATORY TECH SR.
Signature	(Electronic Submission)	Date	01/22/2020

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By	ACCEPTED	Title	JOE KILLINS ENGINEER	Date	01/23/2020
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Farmington			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

AN

3

Additional data for EC transaction #500369 that would not fit on the form

32. Additional remarks, continued

@ 2985'. PBTD @ 3047'. ND BOP. NU WH & ROD STRING. PMP SEATED @ 2967'. LOAD TBG W/PROD H2O, PT TBG TO 1500 PSI, GOOD TEST. LONG STROKE PMP & TEST TO 500 PSI, GOOD PMP ACTION.

RDRR @ 1200 hrs ON 1/16/2020.

Email sent to Brandon @ OCD and Joe @ BLM to update about leaving Fish in the hole. Both agencies are okay with it being left.

Well Name: VANDERSLICE #100

API / UWI 3004526907	Surface Legal Location 018-032N-010W-A	Field Name CEDAR HIL F B C #2895	Route 0104	State/Province NEW MEXICO	Well Configuration Type
Ground Elevation (ft) 6,330.00	Original KB/RT Elevation (ft) 6,343.00	KB-Ground Distance (ft) 13.00	KB-Casing Flange Distance (ft)	KB-Tubing Hanger Distance (ft)	

Original Hole, 1/17/2020 8:19:24 AM
