



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 2.6.20 Operator Dugan Rod API # 30-0 45.33217

Property Name Herry Monster Well # 3 Location: Unit F Sec 11 Twn 24 Rge 11

Land Type:

State _____
Federal /
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal /
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

NMOC
FEB 06 2020
DISTRICT III

Temporarily Abandoned Well (Y/N): 0 TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. 0 Max. Inj. Pres. 1379
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 0
Int. Casing Pres. N/A

Pressured annulus up to 400 psi. for 30 mins. Test passed/failed passed

REMARKS: Rose 275: at end-

ID 7082 Packer set 6826 top of 6916 7080

By Jason Herber (Operator Representative) Witness Monica Tuckman (NMOC)

(Position)

Revised 02-11-02

