



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(~~TA~~ OR UIC)

Date of Test 3-2-2020 Operator Pride Energy Co. API # 30-043-20729

Property Name San Isidro 7 Well # 11 Location: Unit K Sec 7 Twn 2N Rge 2W

Land Type:

State _____
Federal X
Private _____
Indian _____

NMOCD
MAR 03 2020
DISTRICT III

Well Type:

Water Injection X
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (~~TA~~ N): Post Workover TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. ✓ Max. Inj. Pres. 488
Bradenhead Pres. 0 light puff Tbg. Inj. Pres. ✓
Tubing Pres. 0 tubing not hooked up to pump
Int. Casing Pres. _____

Pressured annulus up to 405 psi. for 30 mins. Test passed ~~failed~~

REMARKS: Pressured up to 405psi - had slight drop to 400psi in first - temp line red - capped and restart.
405psi held at 405psi for entire test

Packer set 2343' 1000 # spring 1 hr clock/chart ^{last cal.} 2-25-20

By Jahmy May Jr
(Operator Representative)

Witness J
(NMOCD)

(Position)

Revised 02-11-02