submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED	5. Lease Number
7. T . 1 . 1 . 1 . 1	
and the second s	NMSF-079522 6. If Indian, All. or Tribe Name
Name of Operator BURLINGTON	7. Unit Agreement Name San Juan 28-5 Unit
2 V (20 mm)	8. Well Name & Number
Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	San Juan 28-5 Unit #68P 9. API Well No.
Landar CWALL France Co. T. D. M.	30-039-29819
Location of Well, Footage, Sec., T, R, M Sec., TN, RW, NMPM	10. Field and Pool
Unit L (NWSW) 2620' FSL & 10' FWL, Sec. 33, T28N, R5W NMPM	Blanco Mesaverde/Basin Dakota
	11. County and State Rio Arriba Co., NM
CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTH Type of Submission Type of Action Abandonment Recompletion Plugging Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection	ER DATA X Other – Spud Report
. Describe Proposed or Completed Operations	
15/06 MIRU Mote #1. Spud 12 ¼" @ 0900 5/15/06. Drilling ahead to 137'. Circulate hole. RIH TC CSG and set @ 134'. Pumped preflush 6bbls H2O. Pumped 50sxs(81cu-14bbls)Type 1-2 Por ag and displaced w/7bbls H2O. Circulated 3bbls of cmt to surface. WOC. Install wellhead. RD Manducted by drilling rig and shown on next report.	rtland cmt w/20% flyash. Drop
4. I hereby certify that the foregoing is true and correct.	
gned Amanda Sandoval Title Regul	atory Analyst Date 5/16/06
his space for Federal or State Office use) PPROVED BY Title	Date

NIJOED S MAY 1 7 2006
FARRINGTON FEED OFFICE

Swa