

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test_4/25/06Operator_Burlington I	Resources Oil & GasA	API <u>#30-045-0561</u>	<u>.1</u>
Property Name Wilson A Well No. 2 Loc	ation: Unit_K_Section_3	2Township_ <u>26</u>	N_Range_8W_
Pressure (Flowing) Tubing 0 Intermediate	Casing 3 Brad	denhead_0_	
OPEN BRADENHEAD AND INTERMEDIATE TO	O ATMOSPHERE INDIVII	DUALLY FOR 15	MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flow		
10 minutes	Surges		
15 minutes	_ Down to Nothing_		
20 minutes	Nothing	X	
25 minutes	_ Gas		
30 minutes	Gas & Water		71.75 7F 250
	Water		2 CHENCOS / SPECIAL
If bradenhead flowed water, check all of the descriptions	that apply below:		MAY 2006
CLEARFRESHSALTY	SULFURBLACK_		CL S. DW. 23
5 MINUTE SHUT-IN BRADENHEAD 0	INTERMEDIATE	- -	it as 8 1977
REMARKS: No Pressure on BH. Well was restimulated 1/30/97 returned to production. Well has no tbg Order.		ed to surface, per	f'd, frac'd,
By Contractor- Jesse Randall run 383 Witness	,		_
Lease Operator (Position)			
F-mail address nthompson@hr-inc.com Philana	Thompson - Regulatory Anal	vet	