

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

See Date
Date of Test _____ Operator Dugan Production Corp. API # 30-045-32285
Property Name Pseudo FR Coal Mine Gas Well No. 1 Location: Unit N Section 23 Township 30N Range 15W
Well Status(Shut-In or Producing) Initial PSI: Tubing N/A Intermediate N/A Casing N/A Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes						
10 minutes						
15 minutes						
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

not in operation - vent shaft.

By *Armando Fune* _____
Switcher
(Position)

Witness _____