

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 05-19-06 Operator Dugan Production Corp. API # 30-045-05750
Property Name West Bisti Unit Well No. 114 Location: Unit L Section 20 Township 26N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 70 Intermediate N/A Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

	Bradenhead			Interm	
TIME	BH	Int	Csg	Int	Csg
5 minutes	0		70		
10 minutes	0		70		
15 minutes	0		70		
20 minutes					
25 minutes					
30 minutes					

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

INTERMEDIATE

REMARKS:

By

Rodolfo Hernandez
Switcher
(Position)

Witness