

1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	6/1/2006	Operator	Burlington Resources Oil & Gas
--------------	----------	----------	--------------------------------

Lease Name HUERFANITO UNIT Well No 86 Location: U L Sec. 36 Twp. 027N Rge. 009W

Pressure (Shut-in) Dwt	Tubing	71	Intermediate	Casing	80	Bradenhead	55
------------	---------	-------	--------	----	--------------	--------	----	------------	----

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:		BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
	INTERMEDIATE	CASING		
5 Min.		80	Steady Flow	
10 Min.		81	Surges	
15 Min.		81	Down to Nothing	
20 Min.		81	Nothing	
25 Min.		81	Gas	X
30 Min.		81	Gas & Water	
			Water	

If Bradenhead flowed water, check description below:

Clear _____

Fresh _____

Salty _____

Sulfur _____

Black _____

Remarks: Too Small To Measure
Ending: BH Press.: 0 Interm. Press.
BR BLEW DOWN IN 1 MIN. PUMP JACK
DOWN DUE TO HOLE IN TUBING. BR AT 0
AFTER 5 MIN.
SHUTIN

By DENNIS JACQUEZ 309
Lease Operator

Position

Witness

