



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6172 FAX: (505) 334-6170
<http://emard.state.nm.us/ocd/District/IV/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-1-06 Operator Yates Peteckum API #30-0 45-29198
Property Name Rocco 12 Well No. 2 Location: Unit H Section 12 Township 29 N Range 13 W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 25 Bradenhead 24

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		25#		
10 min	0		25#		
15 min	0		25#		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>10 sec</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

Bradenhead Head 24 Blew to nothing 10 sec
Well is on Pumping Unit Going to CDP Compressor

By Joe Fero
Pumper
(Position)

Witness David Dempsey

E-mail address

