

1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	6/5/2006	Operator	Burlington Resources Oil & Gas
--------------	----------	----------	--------------------------------

Lease Name ALLISON UNIT Well No 111S Location: U J Sec. 18 Twp. 032N Rge. 006W

Pressure (Flowing) Dwt	Tubing	1	Intermediate	Casing	29	Bradenhead	40
------------	---------	-------	--------	---	--------------	--------	----	------------	----

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:		BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
	INTERMEDIATE	CASING		
5 Min.		29	Steady Flow	
10 Min.		29	Surges	
15 Min.		29	Down to Nothing	X
20 Min.			Nothing	
25 Min.			Gas	X
30 Min.			Gas & Water	
			Water	

If Bradenhead flowed water, check description below:

Clear _____

Fresh _____

Salty _____

Sulfur _____

Black _____

Remarks:

Ending: BH Press.: 0 Interm. Press.

Checked and recorded pressures. Braidenhead had 40 PSI. It blew down immediately and had no flow after that. after being open for 15 minutes it was shut for 5 minutes and there was 0 PSI.

By PATRICK HUDMAN 361

Lease Operator

Position

Witness