

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other Instructions on reverse side

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. <i>nm 052931</i>
2. Name of Operator <i>BCED Oil and Gas Corp.</i>		6. If Indian, Allottee or Tribe Name
3a. Address <i>P.O. Box 1680 Hobbs, NM</i>	3b. Phone No. (include area code) <i>505-397-3972</i>	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) <i>2060' FWL, 630' FSL Sec. 6, T11N, R8W</i>		8. Well Name and No. <i>Hansen 16</i>
		9. API Well No. <i>30-031-20144</i>
		10. Field and Pool, or Exploratory Area <i>HOSPAN Dakota</i>
		11. County or Parish, State <i>McKinley, NM</i>

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input checked="" type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

PLS SEE Attachment



14. I hereby certify that the foregoing is true and correct	
Name (Printed/Typed) <i>Donnie Hill</i>	Title <i>President</i>
Signature <i>Donnie Hill</i>	Date <i>2/20/03</i>

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NO RPT PROD + 3-01

PROD DK

ATTACHMENT

HANSON FEDERAL # 16
NM 052931
30-031-20144
SEC.6,T17N,R8W

THE SUBJECT WELL HAD A NOTICE OF INTENT TO P&A THE UPPER SAND INTERVAL AND DEEPEN TO THE HOSPAH DAKOTA IN SEPT. 1987 BY TESORO PETROLEUM. THE WORKOVER WAS CONDUCTED HOWEVER TESORO NEVER SUBMITTED A SUBSEQUENT REPORT INDICATING THE WORK BEING PERFORMED. THE ATTACHED 3160-4 (WELL COMPLETION REPORT) WAS SUBMITTED VERIFYING THE WORK COMPLETED.

THE WELL IS CURRENTLY COMPLETED IN THE HOSPAH DAKOTA AND IS PRODUCING GAS FOR LEASE USE ONLY.

THE UPPER SAND INTERVAL IS CURRENTLY P&AD.

**** 4 3/4" HOLE FROM 1515' TO 2770'**

**** 3 1/2" LINER FROM SURFACE TO TD (105 SXS)**

**** CEMENT CIRCULATED TO SURFACE**

**** PERFORATIONS @ 2496'- 2511'**

**** 2 1/16" TUBING INSTALLED**