

1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4/10/2006 Operator Burlington Resources Oil & Gas

Lease Name HUERFANO UNIT Well No 244E Location: U A Sec. 19 Twp. 026N Rge. 010W

Pressure (T/A Shut-in) Dwt Tubing 1 Intermediate Casing 1 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:		BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
	INTERMEDIATE	CASING		
5 Min.		1	Steady Flow	
10 Min.		1	Surges	
15 Min.		1	Down to Nothing	
20 Min.		1	Nothing	X
25 Min.		1	Gas	
30 Min.		1	Gas & Water	
			Water	

If Bradenhead flowed water, check description below:

Clear _____

Fresh _____

Salty _____

Sulfur _____

Black _____

Remarks:

Ending: BH Press.: 0 Interm. Press.


Well has a down hole plug and cement. The tubing and casing are 0 but the computer won't let me enter 0. This well is due to be recompleted in upper zone. **TAD** 10/29/1

By JOE GOLDING 370

Lease Operator

Position

Witness



TA Expires 12/15/00
OCD