

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-144
June 1, 2004

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes ☒ No ☐

Type of action: Registration of a pit or below-grade tank ☐ Closure of a pit or below-grade tank ☒

Operator: BP AMERICA PROD. CO. Telephone: 505-326-9200 e-mail address: _____
Address: 200 ENERGY COURT, FARMINGTON, NM 87410
Facility or well name: MUDGE A #5A API #: 30-045- 22509 U/L or Qtr/Qtr C Sec 3 T 31N R 11W
County: SAN JUAN Latitude 36.93185 Longitude 107.98048 NAD: 1927 ☐ 1983 ☒ Surface Owner Federal ☒ State ☐ Private ☐ Indian ☐

Pit Type: Drilling <input type="checkbox"/> Production <input type="checkbox"/> Disposal <input checked="" type="checkbox"/> <u>BLOW</u> Workover <input type="checkbox"/> Emergency <input type="checkbox"/> Lined <input checked="" type="checkbox"/> Unlined <input type="checkbox"/> <u>STEEL TANK</u> Liner type: Synthetic <input type="checkbox"/> Thickness _____ mil Clay <input type="checkbox"/> Pit Volume _____ bbl	Below-grade tank Volume: _____ bbl Type of fluid: _____ Construction material: <u>N/A</u> Double-walled, with leak detection? Yes <input type="checkbox"/> If not, explain why not. _____	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet	(20 points)
	50 feet or more, but less than 100 feet	(10 points) 0
	100 feet or more	(0 points)
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes	(20 points)
	No	(0 points) 0
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet	(20 points)
	200 feet or more, but less than 1000 feet	(10 points) 0
	1000 feet or more	(0 points)
Ranking Score (Total Points)		0

If this is a pit closure: (1) attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if you are burying in place) onsite ☒ offsite ☐ If offsite, name of facility _____. (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No ☒ Yes ☐ If yes, show depth below ground surface _____ ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations.

Additional Comments: PIT LOCATED APPROXIMATELY 120 FT. S38W FROM WELL HEAD
PIT EXCAVATION: WIDTH N/Aft., LENGTH N/Aft., DEPTH N/Aft.
PIT REMEDIATION: CLOSE AS IS: ☒, LANDFARM: ☐, COMPOST: ☐, STOCKPILE: ☐, OTHER ☐ (explain)
Cubic yards: N/A
BEDROCK BOTTOM, NO TPH ANALYSIS CONDUCTED Bedrock



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐, or an alternative OCD-approved plan ☒.

Date: 05/20/05

Printed Name/Title Jeff Blagg - P.E. # 11607 Signature Jeff Blagg

Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.

Approval: _____
Printed Name/Title DEPUTY OIL & GAS INSPECTOR, DIST. # Signature Wendy Fatt Date: FEB 21 2006

CLIENT: <u>BP</u>	BLAGG ENGINEERING, INC. P.O. BOX 87, BLOOMFIELD, NM 87413 (505) 632-1199	LOCATION NO: <u>B1528</u> COCR NO: <u>—</u>																																										
FIELD REPORT: PIT CLOSURE VERIFICATION		PAGE No: <u>1</u> of <u>1</u>																																										
LOCATION: NAME: <u>MUDGE A</u> WELL #: <u>5A</u> TYPE: <u>BLOW</u> QUAD/UNIT: <u>C SEC: 3 TWP: 31N RNG: 11W PM: NM CNTY: ST: NM</u> QTR/FOOTAGE: <u>815'N/1663'W</u> NE/NW CONTRACTOR: <u>HDI (LIONELL)</u>		DATE STARTED: <u>5/20/05</u> DATE FINISHED: <u>—</u> ENVIRONMENTAL SPECIALIST: <u>NV</u>																																										
EXCAVATION APPROX. <u>NA</u> FT. x <u>NA</u> FT. x <u>NA</u> FT. DEEP. CUBIC YARDAGE: <u>NA</u>																																												
DISPOSAL FACILITY: <u>ON-SITE</u> REMEDIATION METHOD: <u>CLOSE AS IS</u>																																												
LAND USE: <u>RANGE - BLM</u> LEASE: <u>3F 078040</u> FORMATION: <u>MV</u>																																												
FIELD NOTES & REMARKS: PIT LOCATED APPROXIMATELY <u>120</u> FT. <u>S38W</u> FROM WELLHEAD.																																												
DEPTH TO GROUNDWATER: <u>>100'</u> NEAREST WATER SOURCE: <u>>1,000</u> NEAREST SURFACE WATER: <u>>1,000</u>																																												
NMOCD RANKING SCORE: <u>0</u> NMOCD TPH CLOSURE STD: <u>5000</u> PPM																																												
SOIL AND EXCAVATION DESCRIPTION: <u>ELEV - 6132'</u>																																												
OVM CALIB. READ. = <u>53.8</u> ppm OVM CALIB. GAS = <u>100</u> ppm RF = 0.52 TIME: <u>10:10</u> am/pm DATE: <u>5/20/05</u>																																												
SOIL TYPE: <u>SAND</u> SILTY SAND / SILT / SILTY CLAY / CLAY / GRAVEL / OTHER <u>BEDROCK (SHALE)</u>																																												
SOIL COLOR: <u>OK. YELL. BROWN</u> <u>BEDROCK - LT. BLUE</u>																																												
COHESION (ALL OTHERS): <u>NON COHESIVE</u> SLIGHTLY COHESIVE / COHESIVE / HIGHLY COHESIVE																																												
CONSISTENCY (NON COHESIVE SOILS): <u>LOOSE</u> / FIRM / DENSE / VERY DENSE																																												
PLASTICITY (CLAYS): NON PLASTIC / SLIGHTLY PLASTIC / COHESIVE / MEDIUM PLASTIC / HIGHLY PLASTIC																																												
DENSITY (COHESIVE CLAYS & SILTS): SOFT / FIRM / STIFF / VERY STIFF / HARD																																												
MOISTURE: DRY / SLIGHTLY MOIST / MOIST / WET / SATURATED <u>SUPER SATURATED</u>																																												
DISCOLORATION/STAINING OBSERVED: YES / <u>NO</u> EXPLANATION - <u>CLOSED</u>																																												
HC ODOR DETECTED: YES / <u>NO</u> EXPLANATION - <u>—</u>																																												
SAMPLE TYPE: <u>GRAB</u> COMPOSITE - # OF PTS. <u>—</u>																																												
ADDITIONAL COMMENTS: <u>45 BBL STEEL TANK REMOVED PRIOR TO ARRIVAL. STANDING WATER IN PIT FROM BEDROCK BOTTOM. RECENT PRECIP. ADVANCED TEST HOLE ADJACENT TO PIT TO TRANSFER WATER THEN ADVANCED TEST HOLE IN PIT CENTER. COLLECTED SAMPLE FROM BEDROCK - VERY HARD, COMP.</u>																																												
FIELD 418.1 CALCULATIONS																																												
<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>SAMP. TIME</th> <th>SAMP. ID</th> <th>LAB NO.</th> <th>WEIGHT (g)</th> <th>mL FREON</th> <th>DILUTION</th> <th>READING</th> <th>CALC. (ppm)</th> </tr> </thead> <tbody> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table>			SAMP. TIME	SAMP. ID	LAB NO.	WEIGHT (g)	mL FREON	DILUTION	READING	CALC. (ppm)																																		
SAMP. TIME	SAMP. ID	LAB NO.	WEIGHT (g)	mL FREON	DILUTION	READING	CALC. (ppm)																																					
<div style="display: flex; justify-content: space-between;"> <div style="width: 30%;"> <p>SCALE</p>  <p>0 FT</p> </div> <div style="width: 65%;"> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2">PIT PERIMETER</th> <th colspan="2">OVM READING</th> <th colspan="2">PIT PROFILE</th> </tr> <tr> <th>SAMP. TIME</th> <th>SAMP. ID</th> <th>LAB NO.</th> <th>WEIGHT (g)</th> <th>mL FREON</th> <th>DILUTION</th> </tr> </thead> <tbody> <tr><td>1 @ 5'</td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td>2 @ </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td>3 @ </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td>4 @ </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td>5 @ </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table> </div> </div>			PIT PERIMETER		OVM READING		PIT PROFILE		SAMP. TIME	SAMP. ID	LAB NO.	WEIGHT (g)	mL FREON	DILUTION	1 @ 5'						2 @						3 @						4 @						5 @					
PIT PERIMETER		OVM READING		PIT PROFILE																																								
SAMP. TIME	SAMP. ID	LAB NO.	WEIGHT (g)	mL FREON	DILUTION																																							
1 @ 5'																																												
2 @																																												
3 @																																												
4 @																																												
5 @																																												
<div style="display: flex; justify-content: space-between;"> <div style="width: 30%;"> <p>PIT PERIMETER</p>  </div> <div style="width: 65%;"> <p>OVM READING</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>SAMPLE ID</th> <th>FIELD HEADSPACE (ppm)</th> </tr> </thead> <tbody> <tr><td>1 @ 5'</td><td>0.0</td></tr> <tr><td>2 @ </td><td> </td></tr> <tr><td>3 @ </td><td> </td></tr> <tr><td>4 @ </td><td> </td></tr> <tr><td>5 @ </td><td> </td></tr> </tbody> </table> <p>LAB SAMPLES</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>SAMPLE ID</th> <th>ANALYSIS</th> <th>TIME</th> </tr> </thead> <tbody> <tr><td> </td><td> </td><td>1003</td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> </tbody> </table> </div> </div>			SAMPLE ID	FIELD HEADSPACE (ppm)	1 @ 5'	0.0	2 @		3 @		4 @		5 @		SAMPLE ID	ANALYSIS	TIME			1003																								
SAMPLE ID	FIELD HEADSPACE (ppm)																																											
1 @ 5'	0.0																																											
2 @																																												
3 @																																												
4 @																																												
5 @																																												
SAMPLE ID	ANALYSIS	TIME																																										
		1003																																										
<p>NO TPH ANALYSIS WAS CONDUCTED</p> <p>NOT APPLICABLE</p> <p>WATER FROM PIT LATER PUMPED OUT ACCORDING TO BP PERSONNEL (HARRY T.)</p>																																												
TRAVEL NOTES: CALLOUT: <u>5/20/05 - MORN.</u> ONSITE: <u>5/20/05 - MORN.</u>																																												