District 1 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District !!! 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe

Form C-144

June 1, 2004

office

## Pit or Below-Grade Tank Registration or Closure Is pit or below-grade tank covered by a "general plan"? Yes X No ...

Type of action: Registration of a pit or below-grade tank 🔲 Closure of a pit or below-grade tank 🔀					
O company (505)226 0200 a mail address					
Operator: BP America Production Company Telephone: (505)326-9200 e-mail address:					
Address: 200 Energy Ct, Farmington, NVI 67401	Address: 200 Energy Ct, Farmington, NM 87401  Facility or well name: HPTON # R API #: 30-045-26990 U/L or Qtr/Qtr F Sec 28 T 31N R 9W				
County: San Juan Latitude Surface Owner: Federal State Private Indian	Longitude	NAD: 1927 🗆 1983 🗆			
	I Delevered Arch				
Pit Type: Drilling Production X Disposal	Below-grade tank				
Workover  Emergency	Volume:bbl Type of fluid:				
i	Construction material:  Double-walled, with leak detection? Yes  If not.	avalaia viku aat			
Lined Unlined Thislesses	Bouble-wanted, with leak detection? Tes [] If not	, explain why not.			
Liner type: Synthetic Thicknessmil Clay					
Pit Volumebbl	Less than 60 Con	I (20			
Depth to ground water (vertical distance from bottom of pit to seasonal	Less than 50 feet	(20 points)			
high water elevation of ground water.)	50 feet or more, but less than 100 feet	(10 points)			
	100 feet or more	( 0 points)			
Wellhead protection area: (Less than 200 feet from a private domestic	Yes	(20 points)			
water source, or less than 1000 feet from all other water sources.)	No	( 0 points)			
	Less than 200 feet	(20 points)			
Distance to surface water: (horizontal distance to all wetlands, playas,	200 feet or more, but less than 1000 feet	(10 points)			
irrigation canals, ditches, and perennial and ephemeral watercourses.)	1000 feet or more	( 0 points)			
		( o position)			
	Ranking Score (Total Points)				
If this is a pit closure: (1) Attach a diagram of the facility showing the pit'	s relationship to other equipment and tanks. (2) Indica	ate disposal location: (check the onsite box if			
your are burying in place) onsite $\square$ offsite $\square$ If offsite, name of facility_	(3) Attach a general d	escription of remedial action taken including			
remediation start date and end date. (4) Groundwater encountered: No $\square$	Yes 🔲 If yes, show depth below ground surface	ft. and attach sample results.			
(5) Attach soil sample results and a diagram of sample locations and excava	tions.				
Additional Comments:					
See Attached Documentation					
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank					
has been/will be constructed or closed according to NMOCD guidelines 🔼, a general permit 🗌, or an (attached) alternative OCD-approved plan 🗍.					
Date: 11/01/2005					
Printed Name/Title Jeffrey C. Blagg, Agent Signature July C. Slegy					
Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or					
otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.					
- Figure 1013.					
Approval: CENTRY OF R GAS MASSES OF THE PROPERTY OF A COLUMN TO THE PROPERTY OF THE PROPERTY O					
Approval: © GAS MASTELLOR. DAST. 69  Printed Name/Title	Signature Brash Tell	Date: UEC 1 6 2005			
	- June y - C				

BLAGG ENGINEERING, INC. P.O. BOX 87, BLOOMFIELD, NM 87413 (505) 632-1199			13	OCATION NO:	10959			
FIELD RE	PORT:	PIT CL	OSURE	VERIF	CATIO	N P	AGE No:	of
LOCATION: NAME	HORT	o N	WELL #:	Z TYPE	DEHY		ATE STARTED:	1111
QUAD/UNIT: F s	<del></del>						ATE FINISHED:	\$/21/03
QTR/FOOTAGE: /						SF	PECIALIST:	Jes
-EXCAVATION-A	_		<u>8</u> FT.	x <u>7.5</u> FT	. DEEP. CL	JBIC YA	RDAGE:	
DISPOSAL FACILIT		$\sim$ $\sim$ $\sim$ $\sim$		REMEDIA			CLOSE A	5 (S
	NGE - BL			4NM 091.			ATION:	
FIELD NOTES &				(IMATELY 15			_	
DEPTH TO GROUNDWA	()	_		>1000		URFACE \	WATER:	<u>/ 0000</u>
NMOCD RANKING SCO				5000 PF		READ -	130.2 ppm	
SOIL AND EXC	CAVATION	DESCRIPT	<u>ION:</u>		OVM CALIB.	GAS =	250 ppm	
						/S am	/pm DATE: _	5/27/03
SOIL TYPE: SAND	SILTY SAND	O YTISILTY C LAT	CLAY / CLAY /	GRAVEL / OTH	ER			
COHESION (ALL OTHER	- •				COHESIVE			
CONSISTENCY (NON C PLASTICITY (CLAYS): 1		•			/ HIGHLY PLASTI	IC		
DENSITY (COHESIVE C	LAYS & SILTS):	SOFT / FIRM / STI	FF / VERY STIFF	/ HARD	, moner i bion	.0	6	OSED
MOISTURE: DRY SLIG	HTLY MOISTY M	OIST LWET / SAT	URATED / SUPE	R SATURATED	<b>.</b>			
DISCOLORATION/STAIN HC ODOR DETECTED:	TES NO EXPL	ANATION - V	. MINUR	<u> </u>	010			
SAMPLE TYPE GRAB	COMPOSITE . #	OF PTS	± 1.1 2	1 PRI <	ci ta il	/ <b>1</b>	-s Rock	//.٧
ADDITIONAL COMMENT	s: <u>wood</u> Rev	WUE TAN	1 W 2	BBL STE	III set			Teel
	tank	@ this	SPOT					
SCALE			T	LD 418.1 CALC		I		
	SAMP. TIME	SAMP. ID	LAB NO.	WEIGHT (g)	mL FREON	DILUTI	ONREADING	CALC. (ppm)
0 FT								
,\ PIT PF	RIMETE	R	<del></del>	<u> </u>	<u> </u>	PIT	PROFIL	E
7		TANK	0	VM		<u></u>		
l		μ	REA	DING FIELD HEADSPACE	_			
_	a' .	PRINT	ID	(ppm) / 79				
	3		2@		_			
		TH	3 @ 4 @					
F		10'BG	5@		<del></del>	**		
8'	Ø	SAMPLE			<b>-</b>	ot .	APPLICA	BLE
		- PD			-			
		7.5 BG	LARS	AMPLES	<del></del>			
·		1.7 00	CAMOLE	NALYSIS TIME				
	l <del>T</del> n	Ü	10 10 TP	4/BTEX 1345	-			
	WELL		(हनाम ह	ASSED				
'.D. = PIT DEPRESSION; E .H. = TEST HOLE; ~ = AP					_			
TRAVEL NOTES:	CALLOUT: _	5/27/03	1030	ONSITE:	5/27/0	3 /	330	
		/ /			//			



## EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	Blagg / BP	Project #:	94034-010
Sample ID:	Dehy #1 @ 10'	Date Reported:	05-29-03
Laboratory Number:	25748	Date Sampled:	05-27-03
Chain of Custody No:	10959	Date Received:	05-28-03
Sample Matrix:	Soil	Date Extracted:	05-28-03
Preservative:	Cool	Date Analyzed:	05-28-03
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	3.9	0.2
Diesel Range (C10 - C28)	83.2	0.1
Total Petroleum Hydrocarbons	87.1	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

Horton #2.

Analyst C. Orlina

Mistari Malters
Review



## EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Blagg / BP	Project #:	94034-010
Sample ID:	Dehy #1 @ 10'	Date Reported:	05-28-03
Laboratory Number:	25748	Date Sampled:	05-27-03
Chain of Custody:	10959	Date Received:	05-28-03
Sample Matrix:	Soil	Date Analyzed:	05-28-03
Preservative:	Cool	Date Extracted:	05-28-03
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	ND	1.8	
Toluene	45.6	1.7	
Ethylbenzene	53.1	1.5	
p,m-Xylene	232	2.2	
o-Xylene	106	1.0	
Total BTEX	437		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	96 %
	1,4-difluorobenzene	96 %
	Bromochlorobenzene	96 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Horton #2.

Analyst C. Oglewan

Misterien Warters
Review