

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170


http://emrmd.state.nm.us/ocd/District_III/3district.htm

BRADENHEAD TEST REPORT
(Submit 1 copies to above address)

Date of Test 6/6/06 Operator Dugan Production Corp. API # 30-045-24420
Property Name Harvey Well No. 2 Location: Unit F Section 20 Township 24N Range 9W
Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate _____ Casing 35 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	BRADENHEAD		INTERMEDIATE	
	BH	Int	Csg	Int	Csg					
5 minutes	5		35			Steady Flow				
10 minutes	5		35			Surges				
15 minutes	4		35			Down to Nothing	X			
20 minutes	4		35			Nothing				
25 minutes	0		35			Gas				
30 minutes	0		35			Gas & Water				
						Water				



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By [Signature]
Switcher
(Position)

Witness _____