

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emrnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 10/07/06 Operator Dugan Production Corp. API # 30-045-24713
Property Name Billie Well No. 2 Location: Unit L Section 35 Township 22N Range 8W
Well Status(Shut-In or Producing) Initial PSI: Tubing 3 Intermediate _____ Casing 46 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


PRESSURE						FLOW CHARACTERISTICS	
TIME	Bradenhead			Interm		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	0		46			Steady Flow	
10 minutes	0		46			Surges	
15 minutes	0		44			Down to Nothing	
20 minutes	0		44			Nothing	
25 minutes	0		44			Gas	
30 minutes	0		46			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By 
Switcher
(Position)

Witness _____

