

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copies to above address)

Date of Test 6-13-06 Operator Dugan Production Corp. API # 30-045-26814  
Property Name Mary Lou Well No. 6 Location: Unit M Section 32 Township 24N Range 10W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 35 Intermediate 40 Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		40		
10 minutes	0		40		
15 minutes	0		40		
20 minutes	0		40		
25 minutes	0		40		
30 minutes	0		40		

Steady Flow

Surges

Down to Nothing

Nothing

Gas


Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

X	



**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Mike Seward  
Switcher  
(Position)

Witness \_\_\_\_\_