District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410

State of New Mexico Energy Minerals and Natural Resources

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Form C-144

June 1, 2004

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 Pit or Below-Grade Tank Registration or Closure

	k covered by a "general plan"? Yes No or below-grade tank Closure of a pit or below-gra			
Operator: BP AMERICA PROD. CO. Address: 200 ENERGY COURT. FARMINGTON. Facility or well name: ROELOFS #2E County: SAN JUAN Latitude 36.73031 Longitude 10		uil address:		
Pit Type: Drilling Production Disposal PRODUCTION TANK Workover Emergency Lined Unlined Liner type: Synthetic Thickness mil Clay Pit Volume bbl	Below-grade tank Volume:bbl Type of fluid: Construction material: Double-walled, with leak detection? Yes If not explain why not			
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) (0 points)		
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) 0		
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points)		
	Ranking Score (Total Points)	0		
If this is a pit closure: (1) attach a diagram of the facility showing the pit's your are burying in place) onsite ☑ offsite ☐ If offsite, name of facility_remediation start date and end date. (4) Groundwater encountered: No ☑ Yattach soil sample results and a diagram of sample locations and excavation Additional Comments: PIT LOCATED APPROXIMATELY	. (3) Attach a general of Yes If yes, show depth below ground surface Yes FT. S8W FROM WE	description of remedial action taken including ft. and attach sample results. (5)		
PIT EXCAVATION: WIDTH N/Aft., LENGTH		The second second		
PIT REMEDIATION: CLOSE AS IS: ⊠, LANDFARM: □, C	OMPOST: ☐, STOCKPILE: ☐, OTHER ☐ (ex	plain) R ARCENO CO		
Cubic yards: N/A BEDROCK BOTTOM				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit , or an alternative OCD-approved plan .				
Date: 07/25/05 PrintedName/Title Jeff Blagg – P.E. # 11607 Your certification and NMOCD approval of this application/closure does notherwise endanger public health or the environment. Nor does it relieve to regulations.	_SignatureSignatureshould the contents the operator of its responsibility for compliance with a	of the pit or tank contaminate ground water or		
Approval: Printed Name/Title Signature Francha Sound Date: FEB 2 8 2006				



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	Blagg / BP	Project #:	94034-010
Sample ID:	1 @ 2'	Date Reported:	07-25-05
Laboratory Number:	33802	Date Sampled:	07-20-05
Chain of Custody No:	14320	Date Received:	07-21-05
Sample Matrix:	Soil	Date Extracted:	07-22-05
Preservative:	Cool	Date Analyzed:	07-25-05
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

Roelofs 2E Prod. Pit.

Alexa C. Oglina Analyst

Mistin m Walter Review