<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division

Pit or Below-Grade Tank Registration or Closure

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe

Form C-144

June 1, 2004

1220 South St. Francis Dr. Santa Fe, NM 87505

Is pit or below-grade tank covered by a "general plan"? Yes ☐ No ☒ Type of action: Registration of a pit or below-grade tank ☐ Closure of a pit or below-grade tank ☒				
Operator: Dugan Production Corp Telephone: (505)325-1821 e-mail address:				
Address: P.O. Box 420, Farmington, New Mexico 87401				
Facility or well name: Dome Nav. 28-22-6 #2 API #:				
County: Sandoval Latitude 36.10633 Longitude 10				
Pit Below-grade tank				
Type: Drilling Production 🗷 Disposal 🗌	Volume:bbl Type of fluid:	Mitty case		
Workover ☐ Emergency ☐	Construction material: Double-walled, with leak detection? Yes If not, explain why not.			
Lined ☐ Unlined ☑				
Liner type: Synthetic Thicknessmil Clay _		Co Cast 3		
Pit Volume 850 ± bbl				
Depth to ground water (vertical distance from bottom of pit to seasonal	Less than 50 feet	(20 points)		
high water elevation of ground water.)	50 feet or more, but less than 100 feet	(10 points)		
mgii water elevation or ground water.	100 feet or more	(0 points)		
Wellhead protection area: (Less than 200 feet from a private domestic	Yes	(20 points)		
water source, or less than 1000 feet from all other water sources.)	No	(0 points) 0		
water source, or less than 1000 feet from all other water sources.	Less than 200 feet	(20 points)		
Distance to surface water: (horizontal distance to all wetlands, playas,	200 feet or more, but less than 1000 feet	(10 points) 0		
irrigation canals, ditches, and perennial and ephemeral watercourses.)	1000 feet or more	(0 points)		
		0		
	Ranking Score (Total Points)	0		
f this is a pit closure: (1) attach a diagram of the facility showing the pit's	relationship to other equipment and tanks. (2) Indic	cate disposal location: (check the onsite box if		
our are burying in place) onsite 🔀 offsite 🔲 If offsite, name of facility_	. (3) Attach a general	description of remedial action taken including		
emediation start date and end date. (4) Groundwater encountered: No 🔀 Y	Yes I If yes, show depth below ground surface	ft. and attach sample results. (5)		
Attach soil sample results and a diagram of sample locations and excavation	s.			
Additional Comments:				
850 bbl, 3'± deep unlined production pit, center located 87 feet South 8	2° East of wellhead.			
Use Backhoe to dig into pit and sample.				
Collect 4-point composite soil sample from sidewalls and single sample of	of pit center for laboratory testing.			
See attached field sampling report and laboratory test reports.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan . Date: June 13, 2006				
Printed Name/Title Jeff Blagg, Agent Signature Jeff Blagg				
Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Approval: Printed Name/Title Printed Name/Title Approval: Signature Signature Signature Signature				

50-043-20417	36.1063	33 × 10 (.	7006	1			
			NEERING	•	, L	OCATION NO:	
CLIENT: DUGAN	P.O. BOX 8 (5	37, BLO 305) 632), NM 874	113	COCR NO:	14646
FIELD REPORT	r: PIT CLC	SURE	VERIF	ICATIO	N P	AGE No:	of
LOCATION: NAME: DOME						ATE STARTED: 5	
QUAD/UNIT: I SEC: 28	TWP: ZZN RNG:	6W PM: 1	UM CNTY: S.	N ST: N		ATE FINISHED: 5	
QTR/FOOTAGE: [780 FSL	× 830 FEL	CONTR	ACTOR: SIER	LA		NVIRONMENTAL PECIALIST:	ICB
EXCAVATION APPROX				1			0
DISPOSAL FACILITY:					aler .		
LAND USE: RANGE - N		·					
FIELD NOTES & REMARMENT DEPTH TO GROUNDWATER: 20 NMOCD RANKING SCORE: 4	NEAREST WAT	ER SOURCE:	>1000				
SOIL AND EXCAVATION	ON DESCRIPTION	ON:		OVM CALIB.	GAS =	53.9 ppm	RF = 0.52
SOIL TYPE: SAND SILTY SA	ND SILT / SILTY CL	AY / CLAY / (GRAVEL / OTH		an an	n/pm DATE:	18
COHESION (ALL OTHERS): NON C	OHESIVE KSLIGHTLY			COHESIVE			
CONSISTENCY (NON COHESIVE S PLASTICITY (CLAYS): NON PLAST				TO A PLANT OF	10		l
DENSITY (COHESIVE CLAYS & SIL	TS): SOFT / FIRM / STIF	F / VERY STIFF	/ HARD	/ MIGHET FEAG.	iC		
MOISTURE: DRY (SLIGHTLY MOIS DISCOLORATION/STAINING OBSE			R SATURATED				
HC ODOR DETECTED: YES (NO)	EXPLANATION -	ANATION					
SAMPLE TYPE: GRAB / COMPOSIT ADDITIONAL COMMENTS:		- x´± b	era Unlin	ed Pital	EMARG	ED IN SOU	th end.
ADDITIONAL COMMENTS.		USE B	MEHHUE TO	DIG 127	3 PIY	T SAW	06
		FIE	LD 418.1 CAL	THE ATIONS			
SCALE SAMP. TI	ME SAMP. ID	LAB NO.	WEIGHT (g)	T	DILUT	IONREADING	CALC. (ppm)
0 FT							
서 PIT PERIME	ΓER	0			Pl	r PROFIL	<u>.E</u>
1		_	VM JDING				
A		SAMPLE ID	FIELD HEADSPAC	E			
~16-	-	1 @ 2 @					
1	1	3 @			 5	6' —	→
Com 20		4 @ 5 @		_			
4 PECE 0.0 3 1							
36' 20'							
LAB SAMPLES							
1 D	_/	SAMPLE A	NALYSIS TIM				
€ 36'-		C06' T/C	112				
A							
P.D. = PIT DEPRESSION; B.G. = BELO T.H. = TEST HOLE; ~ = APPROX.; T.B.	W GRADE; B = BELOW = TANK BOTTOM				t		
TRAVEL NOTES: CALLOUT: ONSITE: 5/18/06							
ONGITE. THE TOTAL OF THE PARTY							



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	Blagg / Dugan	Project #:	94034-010
Sample ID:	Dome Navajo 28-22-6 #2	Date Reported:	05-25-06
Laboratory Number:	37189	Date Sampled:	05-18 - 06
Chain of Custody No:	14646	Date Received:	05-19-06
Sample Matrix:	Soil	Date Extracted:	05-22-06
Preservative:	Cool	Date Analyzed:	05-24-06
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments: Pit Closures 4 - Point @ 6'.

Analyst Maltes

Hule OVen



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Blagg / Dugan	Project #:	94034-010
Sample ID:	Dome Navajo 28-22-6 #2	Date Reported:	05-25-06
Laboratory Number:	37189	Date Sampled:	05-18-06
Chain of Custody:	14646	Date Received:	05-19-06
Sample Matrix:	Soil	Date Analyzed:	05-24-06
Preservative:	Cool	Date Extracted:	05-22-06
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
	(=33)	(
Benzene	5.5	1.8	
Toluene	7.9	1.7	
Ethylbenzene	3.1	1.5	
p,m-Xylene	9.3	2.2	
o-Xylene	ND	1.0	
Total BTEX	26.5		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	97.0 %
	1,4-difluorobenzene	97.0 %
	Bromochlorobenzene	97.0 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Pit Closures 4 - Point @ 6'.

Musteren Walles

Review

Pul Dall



Chloride

Client: Sample ID: Lab ID#: Blagg / Dugan Dome Navajo 28-22-6 #2 37189 Project #:
Date Reported:
Date Sampled:

94034-010 05-25-06 05-18-06

Sample Matrix: Preservative:

Soil Cool Date Sampled:
Date Received:
Date Analyzed:

05-19-06 05-25-06

Condition:

Cool and Intact

Chain of Custody:

14646

Parameter

Concentration (mg/Kg)

Total Chloride

272

Reference:

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

Pit Closures 4 - Point @ 6'.

Analyst

L Wall

Review